
Horizontal Powerflue - Brick Veneer Wall Detail





note:

- DO NOT SCALE OFF THESE DRAWINGS. All dimensions are in mm.
- It is advisable to secure the flexible flue to prevent movement, vibration and sagging this will also assist in maintaining the required 50mm standoff where required.
- Ensure flashing's, wall claddings or any other building component does not obstruct the horizontal powerflue terminal.
- Construction requirements including venting, moisture control and insulation shown for illustrative purposes only. Confirm specific regulatory requirements.
- The flue terminal will get very hot when in use. Precautions should be taken to protect people and animals from injury.
- This technical sheet must be read in conjunction with the relevant Escea Gas Fireplace Installation Manual, the latest version can be found on our website at **www.escea.com**.


GENERAL CONSTRUCTION AND FINISHES SHOWN INDICATIVE ONLY

Contact the ESCEA Architectural Advisory Team for assistance with the specification of this fire - aa@escea.com

Flue_Install_Details.dwg 04.07.2023

Horizontal Powerflue - Brick Veneer Wall Detail





Jamb Detail scale 1:

note:

- DO NOT SCALE OFF THESE DRAWINGS. All dimensions are in mm.
- It is advisable to secure the flexible flue to prevent movement, vibration and sagging this will also assist in maintaining the required 50mm standoff where required.
- Ensure flashing's, wall claddings or any other building component does not obstruct the horizontal powerflue terminal.
- Construction requirements including venting, moisture control and insulation shown for illustrative purposes only. Confirm specific regulatory requirements.
- The flue terminal will get very hot when in use. Precautions should be taken to protect people and animals from injury.
- This technical sheet must be read in conjunction with the relevant Escea Gas Fireplace Installation Manual, the latest version can be found on our website at **www.escea.com**.

GENERAL CONSTRUCTION AND FINISHES SHOWN INDICATIVE ONLY

Contact the ESCEA Architectural Advisory Team for assistance with the specification of this fire - aa@escea.com

Flue_Install_Details.dwg 04.07.2023